

MARYLAND DEPARTMENT of the ENVIRONMENT
1800 WASHINGTON BOULEVARD
BALTIMORE, MARYLAND, 21230
(410) 537-3000
1-800-633-6101 (within Maryland)
http://www.mde.state.md.us



State of Maryland
Department of the Environment
Emergency Response Division
1800 Washington Blvd. Suite #105
Baltimore, Maryland. 21230-1721



24 HOUR SPILL REPORTING
(Toll Free) 1-866-633-4686
EMERGENCY RESPONSE OFFICE
(410) 537-3975
RESPONSE OFFICE FACSIMILE
(410) 537-3932

PURSUANT TO THE PROVISIONS OF STATE LAW AND REGULATION; (COMAR 26.10.01.03) "A PERSON DISCHARGING OR PERMITTING THE DISCHARGE OF OIL, OR WHO EITHER ACTIVELY OR PASSIVELY PARTICIPATES IN THE DISCHARGE OR SPILLING OF OIL, EITHER FROM A LAND BASED INSTALLATION, INCLUDING VEHICLES IN TRANSIT, OR FROM ANY VESSEL SHIP OR BOAT OF ANY KIND, SHALL REPORT THE INCIDENT IMMEDIATELY TO THE ADMINISTRATION." " THE REPORT OF AN OIL SPILL OR DISCHARGE SHALL BE MADE TO THE ADMINISTRATION IMMEDIATELY, BUT NOT LATER THAN TWO HOURS AFTER DETECTION OF THE SPILL."
*** FIRE DEPARTMENT PERSONNEL, SEE REVERSE ***

ADC Map Coord _____ Date of spill: Mo. 1 2 / Day 0 4 / Yr. 20 1 8 Time of spill: 0 9 1 7 Hours (24 hour clock)
Fire Department Report No.: N/A Police Department Report No.: N/A

Location of spill - Street address: _____
Denton Dining Hall
3951 Denton Service Lane
City / Town College Park, MD
MD County Prince Georges
Zip 20742
Product Name: _____
Cooking Oil / Food Grease
(Indicate Gasoline, Diesel, Heating Oil, Chemical Name or UN ID etc.)
Container Type: _____
Dumpster
(Indicate AST, UST, Transformer, Saddle Tank, Drum etc.)
Capacity of Vessel, Vehicle or Tank: _____
1,210 Gallons
Amount IN Vessel, Vehicle or Tank: _____
20 Gallons
Estimated Amount Spilled: _____
15 Gallons

Transportation Incident: _____
N/A
(Indicate Type of Auto, Truck, Train, Aircraft or Watercraft etc.)
Fixed Facility Incident: _____
Institutional Facility
(Indicate Type of Industrial, Commercial, Residential etc.)
 Contained on Land
 Entered Storm Drain or Ditch
 Entered Sanitary Sewer
 Is Below Ground
 Entered surface waters:
Waterway Name: _____
Vehicle Tag Number and State: _____
N/A
DOT or ICC MC Number: _____
N/A
Hull Numbers and Name: _____
N/A

Person(s) Responsible for Spill: (Driver if Vehicle)
Name: University of Maryland Dining Services
Address: 3951 Denton Service Lane
City/State: College Park, MD Zip: 20742
Phone: 301-405-0562
Drivers Lic.No. N/A State: _____
Company Responsible for Spill: (N/A if private citizen.)
Name: University of Maryland - Office of Environmental Affairs
Address: 4716 Pontiac Street, Suite #0103
City/State: College Park, MD Zip: 20742
Phone: 301-405-3990
Fed. Employer ID No. 52-6002033
Be Sure to Complete Both Sections
Don't Forget to Sign Below

Cause of Spill:
 Motor Vehicle Accident
 Personnel Error/Vandalism
 Tank/Container/Pipe Leak
 Mechanical Failure
 Transfer Accident

Identify All Groups that Participated in Spill Mitigation : Responsible Party
 MDE ERD # _____ # _____
 Federal : _____
 State : _____
 Local : _____
 Contractor: _____
Materials used by You to contain/clean-up spill:
Sorbent Dust: 8 Bags
Sorbent Pads: 12 each or bales
Sorbent Booms: 2 each or bales
Sorbent Sweeps: _____ each or bales
Overpack Drums : _____ ea. Steel or Poly
Other: _____

Responsible Party : Describe circumstances contributing to the spill. (Additional space on back) [Optional for FD or Gov't Personnel]

An unknown employee dumped used cooking oil / grease into a dumpster located adjacent to the Denton Dining Hall loading dock. Dining Services staff notified the Office of Environmental Affairs (OEA) about the leaking oil at 9:17 am. When OEA staff arrived, sawdust had been deployed to contain the spill. OEA staff deployed additional spill response materials inside the dumpster and on the ground. The dumpster was removed from the facility for repair / replacement. All spill cleanup materials were collected and disposed of.

Responsible Party : Describe Containment, Removal and Clean-up operations, including disposal. (Additional space on back) [Optional for FD or Gov't Personnel]

Oil sorbent booms and pads were deployed to contain the spilled cooking oil / food grease. The spill did not reach the stormdrain system or waters of the state. All oil was contained to the paved parking area near the loading dock. All spill cleanup materials were disposed of in a dumpster. The leaking dumpster was removed for repair.

Responsible Party : Procedures, Methods and Precautions instituted to prevent recurrence of the spill. (Additional space on back) [Optional for FD or Gov't Personnel]

Dining Services staff are attempting to identify the employee who dumped the cooking oil / food grease into the dumpster. Staff will be retrained regarding proper oil disposal.

THE UNDERSIGNED CERTIFIES THAT THE INFORMATION PROVIDED IS TRUE AND CORRECT TO THE BEST OF HIS OR HER KNOWLEDGE AT THE TIME THE REPORT WAS COMPLETED.
Print Name: Jason Baer, Assistant Director, Office of Environmental Affairs Company or Fire Department: University of Maryland
Address : 4716 Pontiac Street, Suite, 0103 City / State / Zip College Park, MD 20742
Telephone 301-405-3163 Signature Jason Baer
Digitally signed by Jason Baer
Date: 2018.12.04 15:50:43 -0500